

## Case Study

**Name and location of project:** Volcke aerosol UK



**Client details:** Volcke aerosol UK

**Location:** Cwmbran

**Timescale**

10 DAYS

**Nature of the project-**

To carry out [high level cleaning](#) and degreasing to under roof ceiling tiles steel girders and purlins to allow for [industrial spray painting](#) and re coating

Clean down and degrease all walls to allow for [commercial painting](#)

Carry out all warehouse commercial floor cleaning and degreasing

Clean out all high level roof gutters and window roof lights and [cladding](#)

### **The suggested improvements**

To re paint all surfaces using an industrial washable paint coating to allow for easy future cleaning and to enhance long term visual appearance

### **What we did**

We carried out a fully property survey with the client management team and discussed the various options and approach to the job including the tight working schedule over the Christmas periods

### **Task**

We hired in the specialised lift access equipment

We carried out [high level cleaning](#) and degreasing of the internal steel work, then treated with steel cladding with anti-rust primers to allow for the commercial spray painting team to re coat the walls and steel work

We cleaned out all the high level gutters and valleys to remove moss after treating with [high pressure jet washing](#)

We delivered the project to standard required by the client.

## **Client Testimonial**

"We recently engaged APT to carry out commercial high level cleaning and repainting of our production area. They were very professional and detailed in their management of the project. I will be happy to recommend and continue to use their services in future."

**- Neil Woodford, Factory Maintenance Manager -**

### **Other comments.**

There were obstacles regarding constant movement of other contractors to be considered during the working days these were overcome by implementing a detailed but flexible approach and day to day management